

Coromandel Coastal Walkways

Notes from Meeting held October 2015

The Committee asked Mandy Alexander to follow-up and make further contact with Council in regard to the required Pauanui Board Walk repairs.

The Committee appreciated the support from Council with regards to Engineers Report and are keen to move forward with the necessary repairs as soon as they are able. The report concluded with a recommendation, but did not provide detail of how exactly this should be undertaken ie; working drawing of required bracing between posts, and where exactly the proposed strategic positions would be for installation of the Ancorloc (or similar) braces. The committee deems this essential information to ensure the repairs are undertaken correctly.

The committee are fortunate to be able to source an alternative locking pile system at cost through a member of the committee, along with use of the installation machine required, and have therefore decided to use the 'Blade Pile' system. They now require the specific detail of how posts need to be braced and where these piles need to be installed to ensure the board walk structure is adequately stabilised.

Mandy Alexander
Treasurer
Coromandel Coastal Walkways

Preliminary budget estimate

Blade Pile NZ Ltd 73 Coleridge st. Sydenham, Christchurch Peter Fowler 03 669 2005 021 712 962 Peter@BPNZ.co.nz www.Bladepile.com		<div style="display: flex; justify-content: space-between; align-items: center;"> <div style="font-size: 2em; font-weight: bold; letter-spacing: 0.5em;">BLADE PILE</div> </div> <div style="text-align: center; margin-top: 5px;"> New Zealand </div>			
Customer Information			Quotation Number: Rev: 0 Dated: 9/10/15		
Company	Contacts	Location			
		Pauanui Board walk			
Size	Description		Price/Unit	Q'ty	Total
	Total				
88.9x5.5mm CHS 350mm blade	10 piles x 2m long		3,500	1	3500
					0
	Top bracket not included in costing				0
	Instillation not included				0
	75mm drive head to be attached to Auger supplied on loan. Must be returned within 3 weeks.				0
					0
					0
Sub Total					3,500
GST					525
Budgeted Total					4025
All prices are only estimates					
Special requirements for project					
*Client to provide clear and level site with access for BPNZ contractors *Profiles to be set out and pile layout to be clearly marked. *Additional piles or extensions to achieve loadings will be treated as a variation. *Site fencing, toilets, traffic management if required are not included and if required will be a variation *Site services are the responsibility of the client to clearly mark, BPNZ takes no responsibility for hitting any services. *Engineering services, PS1 and PS4 costs are in addition to this price and +10% admin fee *Any change in design will be a variation. *Timber bearers not supplied or installed for timber floors					